

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 21

Township: 8 North


Range: 2 West

Corner ID: VanBu K-15

Monument Description & Remarks: 5/8" Rebar with cap, "SANDERS LS 2030005". Survey Sign 4ft above ground at pt. B

References On File: Lee Utt survey, Kirk L. & Mark R. Mullis (1991), on file in Recorder Office book 2 page 12-13 and L. Randolph Compton survey, SR 45 & Garrison Chapel Rd (2011), on file in Recorder Office cabinet S2 envelope 43/44

RECOVERY TIE DRAWING
Field Book 45 Page No. 49



- A - 5/8" Rebar with cap
- B - S 86° W 0.12' to Survey Sign on "T" metal fence post
- C - S 86° W 25.42' to MAG nail in 17" Black Walnut
- D - S 80° E 13.85' to MAG nail in 17" Red Oak

Not To Scale
Compass Bearing Magnetic North



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 17th day of June, 2011

Kevin Enright



Administered by the Monroe County Surveyor Review Board

Date: 6-19-2012